



## Installing VDO Series-Z Docking Station USB Driver on Windows XP (32 bit)

1. Plug the Docking Station into an USB Port. The „Found new Hardware Wizard“ will appear:




Select “No, not this time” and click “Next”.

2. Select „Install from a list or specific location (Advanced)“ and click „Next“.
3. Your PC will show the next page of the wizard (see Figure below):




Check „Include this location in the search:“. Click „Browse“ and select the file „MwBridge.inf“ from your PC Sport directory (Default: c:\Program Files\MSoft\PC Sport 2008)  
Click „Next“.

4. Your PC will now automatically install the driver. During the installation the following warning might appear:



Choose „Continue Anyway“.


5. Your PC will finish the installation and the window below will appear:



6. Click „Finish“ to complete the installation

## Appendix A: Ensure that the installation finished without errors

1. Open the device manager (see Appendix B)
2. Expand „Universal Serial Bus Controller“
3. If the installation completed without errors you will see „MegaWin MA100 USB-UART Controller“ in the tree (see Figure below):



## Appendix B: Opening the device manager

1. Right-click „My Computer“, click „Manage“, and then click „Device Manager“. The Device Manager opens as shown in the Figure below: